Wichita, Kansas USA

Service Information Letter

SIL MD200 SERIES-01

Course Deviation Indicator

MD200 Series One-piece unit cover

1. PLANNING INFORMATION

A. Effectivity

This service information is applicable to the MD200 Series Course Deviation Indicators manufactured by Mid-Continent Instrument Co., Inc. This service is optional if the twopiece cover is in good condition and can be reused. However, this service must be performed on any MD200 series unit that has a two-piece cover damaged beyond repair.

B. Reason

Ease of production and repair.

C. Description

This information letter performs a change to the Cover Assembly. It replaces the 8017469-1 Cover, Top and 8017469-2 Cover, Bottom with a one-piece cover.

- Replacement Cover Part Number 9013335-1 for units with one connector, 25 pin (J1).
- Replacement Cover Part number 9013335-2 for units with two connectors, 25 pin (J1) and 9 pin (J2).

D. Approval

FAA and TSO approval not affected

E. Manpower

This Service Information Letter may be accomplished and unit tested in approximately 0.25 person-hours.

F. Material – Cost and Availability

The parts and materials necessary to accomplish this change are available form Mid-Continent Instruments. Refer to Section 3, Material Information, for part numbers. Check for current pricing.

G. Tooling

- PH1x60, Phillips head screwdriver.
- 3/16 Nut driver

H. Weight and Balance

No change.

Electrical load data

No change.

J. Other Publications affected

None.

2. **ACCOMPLISHMENT INSTRUCTIONS**

A. Remove tape from joints and discard.

Letter

- B. Remove six (6) screws (7010515 Screw, 2-56x5/32 Flt Phil) from front of cover and discard.
- C. Remove four (4) screws (6011092 Screw, 2-56x3/16 Pan Phil Blk) from rear of cover and discard.
- D. Remove 8017469-1 Cover, Top and 8017469-2 Cover, Bottom. Note unit part number and serial number. Discard nameplate. (A replacement nameplate may be ordered from Mid-Continent Instruments in addition to a new cover).
- E. Remove six (6) screws (7017676 Screw, 4-40x3/16 Pan Phil Blk) that hold on Backplate (8015422-1 or 8015422-2). Save screws but discard the backplate.
- F. Remove four (4) standoffs (8017535 Standoff, 4-40x3/16 MF SS) from the corners of the PC Board and discard.
- G. Install four (4) of the six (6) screws (7017676) removed earlier to reattach the PC Board.
- H. Carefully slide on replacement cover (9013335-1 or 9013335-2).
- Secure cover using two remaining screws (7017676).
- J. Wrap the joint between the cover and the bezel with tape (8017360).
- K. Attach new nameplate to top of cover in the same orientation as the old nameplate.
- L. Test unit i/a/w test specification TDS155 for MD200-2XX AND TDS160 for MD200-3XX.

3. MATERIAL INFORMATION

Install New	Qty.	Description	Discard	Reuse
9013335-1 or 9013335-2	1	Cover	8017469-1 and 8017469-2	
	1	Backplate	8015422-1 or 8015422-2	
	6	Screw 2-56x5/32 Flt Phil	7010515	
	4	Screw 2-56x3/16 Pan Phil Blk	6011092	
	6	Screw 4-40x3/16 Pan Phil Blk		7017676
8017360	A/R	Tape, Acetate Cloth Blk		
Call factory with unit P/N and S/N	1	Nameplate		